## LASER®

## **Temperature/Humidity Level Meter**

Temperature and humidity meter, with data hold function, auto backlight and auto power-off.



## **Additional Information**

- Temperature range: -10° to +50°C / 14° to 122°F (accuracy +/- 1°C).
- Humidity: 10% to 99%.
- 9V battery included.
- CE, UKCA & RoHS compliant. •

http://lasertools.co.uk/product/6904



CV47 0DF







LASER Kamasa Gunson Onnect Prec

6 Y 🖛

10 May 2024